



P1 Branch connectors



Joining all designs of service cables upto 35mm Made from aluminium alloy Supplied with brass gauze to improve electrical stability when joining copper cores.



More info

Fitting Instructions

Cut the service cables to length and remove the insulation using the connector as a guide. Thoroughly abrade the exposed conductors and loosely fit the connector, ensuring that the conductors are correctly aligned. Fully tighten the socket head screw using a 3/16" A/F hexagonal drive.

Stranded conductors below 16mm² should be doubled and re-doubled and, if copper conductors are to be jointed, they should be wrapped in brass gauze. This not only improved the electrical stability of the interface connection, but also helps to contain the strands to prevent splaying.